



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, IL 60604-3590

5577

AUG 12 2004

Mr. Johnny W. Reising
United States Department of Energy
Feed Materials Production Center
P.O. Box 398705
Cincinnati, Ohio 45239-8705

REPLY TO THE ATTENTION OF
LIBRARY:
FILE: 6646.371
2004 AUG 17 A 8:55
LOG E-1020
FERNALD

RE: OSDF Cell 1 and 2
Cap Inspection

Dear Mr. Reising:

The United States Environmental Protection Agency (U.S. EPA) has completed its review of the United States Department of Energy's (U.S. DOE) On-Site Disposal Facility (OSDF) inspection checklist for the Cell 1 and 2 caps. The inspection checklist documents the Cell 1 and 2 cap inspection completed June 8, 2004.

The inspection report and checklist appear technically adequate. Therefore, U.S. EPA approves the OSDF Cell 1 and 2 cap inspection report.

Please contact me at (312) 886-0992 if you have any questions regarding this matter.

Sincerely,

James A. Saric
Remedial Project Manager
Federal Facilities Section
SFD Remedial Response Branch #2

cc: Tom Schneider, OEPA-SWDO
Jamie Jameson, Fluor Fernald
Tim Poff, Fluor Fernald